



Contractor Accreditation Program Requirements

Bronze

- Completion of the Center for the Polyurethanes Industry (CPI) SPF Health and Safety Online Training by all employees handling products, to be completed every two years
- Contractor affirmation of having a Hazard Communication Program and Respirator Program that meets OSHA requirements
- Completion by at least one employee / rig of the contractor involved in the application of SPF of the Covestro Applicator Information Program, or SPF application training from a Covestro-recognized provider
- Application equipment meets minimum recommendations set by Covestro
- Implementation of Job site Recordkeeping

Silver Insulation – (Certified)

- Meet requirements for Bronze level
- Operational Review performed by Covestro Sales or Technical representative, or delegate

Silver Roofing – (Quality Contractor)

- 5 jobs done within the prior 2 years, with any manufacturer's foam
 - 50,000 minimum ft² done per year
 - Average inspection rating = 8
 - Minimum inspection rating = 6
 - Approved for sales on account
 - Evidence of insurance

Gold Roofing (Quality Professional)

- Meet requirements of Silver level
- 5 jobs annually with Covestro product
- Purchase volume of \$300,000 from Covestro per year
- Average inspection rating of 8 with a minimum inspection rating of 7
- **OSHA 10-hour safety certification for all job site employees**
- Evidence of insurance
- Respond to claims in timely manner